

Plant: John Sevier Fossil Plant (JSF)
Date: December 8, 2023 (Placed in Operating Record)
Subject: Annual CCR Fugitive Dust Control Report
Reference: Title 40
Part 257: *Criteria for Classification of Solid Waste Disposal Facilities and Practices*
Subpart D: *Standards for the Disposal of Coal Combustion Residuals in Landfills and Surface Impoundments*
Operating Criteria: §257.80, *Air Criteria*

1. Introduction

John Sevier Fossil Plant (JSF) was a fossil-fueled, steam-electric generating plant operated by TVA until it was retired in June of 2014. Consequently, coal combustion residuals (CCR) are no longer produced at the plant. The Bottom Ash Pond at JSF is capped and closed. TVA continues to perform maintenance activities and routine inspections of the cap system. Should the cap system be removed and CCR exposed for any reason, applicable best management practice (BMPs) described in the Fugitive Dust Control Plan would be implemented and documented on the CCR website as prescribed in the record-keeping requirements of 40 C.F.R. §257.105, 40 C.F.R. §257.106, and 40 C.F.R. §257.107. This report describes actions taken to control CCR fugitive dust and reports citizen complaints and corrective action taken if any, as required pursuant to 40 C.F.R. § 257.80(c).

2. Fugitive Dust Control Measures

Since the unit is capped and closed, no work was performed during 2023 that would require implementation of fugitive dust BMPs.

3. Record of Citizen Complaints

The CCR Fugitive Dust Control Plan allows for public input by providing a toll-free number for citizens to contact and submit complaints and/or concerns relative to dust control. When complaints are submitted, TVA will assign the appropriate Coal Combustion Product Management (CCPM) personnel to investigate the complaint/concern and implement any additional dust control measures required.

No complaints and/or concerns have been submitted by the public during this reporting period.

4. Summary of Corrective Measures

Corrective measures have not been implemented since dust control measures appear adequate and no complaints/concerns have been submitted.